
# PORT FREEPORT


#### HEAVY LIFT CORRIDOR

# HISTORY



# BENEFITS

- ENHANCED SAFETY FOR CITIZENS DUE TO MINIMIZED TRUCK VOLUMES ON ROADWAYS
- TOTAL TRUCK VOLUMES REDUCED BY 20-22%
- EMISSIONS LOWERED BY 20-22%
- FEES COLLECTED AID IN HWY MAINTENANCE SAVING TAX PAYERS \$
- MANUFACTURER SAVINGS MAKES BRAZORIA COUNTY ATTRACTIVE LONG TERM INVESTMENT OPTION
- CREATES AND MAINTAINS JOBS
- DPS ACCESS TO REAL TIME MONITORING SYSTEM ENSURES COMPLIANCE WITH STATE LAW



240,000 pounds of cargo = 5 Trucks Maximum 80,000 pounds per truck (truck weight + cargo weight)

Activated Heavy Lift Corridor



240,000 pounds of cargo = 4 Trucks Maximum 125,000 pounds per truck (truck weight + cargo weight)

The same amount of cargo moving, but **<u>1 LESS TRUCK</u>** on the road with a Heavy Lift Corridor

1 LESS TRUCK PER 4 TRUCKS EQUALS 20% LESS TRUCKS ON A HEAVY LIFT CORRIDOR

## **RULES & REGULATIONS**

- **PERMITS VALID FOR 24 HRS AND ARE NOT REUSABLE**
- CLIENTS RESPONSIBLE FOR ANY ADDITIONAL MAINTENANCE COST, TICKETS OR FINES RELATED TO THEIR USE OF ROUTES
- > A CERTIFIED WEIGHT TICKET REQUIRED BY TXDOT
- > MAXIMUM TOTAL WEIGHT FOR HLC 125,000 GROSS LBS
- > PF HLC DOES NOT REQUIRE SPECIALIZED EQUIPMENT FOR CONTAINER LOAD. NOT TO EXCEED MAX NET WEIGHT SHOWN ON EACH CONTAINER
- > PF DOES NOT PERMIT LARGE OR HIGH HEAVY CARGO THAT REQUIRES ENGINEERING AND ROUTE PLANNING. PLEASE CONTACT TXDOT'S HL PERMIT DIVISION FOR FURTHER ASSISTANCE.



#### DIRECTIONS FROM DOW PLANT A & B, BASF

- ► TAKE SH288 THROUGH THE CITY OF FREEPORT, TX.
- ► FOLLOW SH288 UNDER HWY 36 AND CONTINUE EAST
- ► MERGE ONTO HWY 36 TO THE INTERSECTION OF 288 & CR 1495
- ► MAKE A LEFT ONTO CR 1495 STAYING IN THE RIGHT LANE
- **CROSS OVER THE RR TRACKS & TURN RIGHT INTO PORT FREEPORT GATE**

**TO BYPASS THE CITY OF FREEPORT** 


- ► CONTINUE ON SH288 UNTIL YOU REACH CR 523
- ► FOLLOW 523 AROUND & OVER THE BRIDGE
- ► TURN LEFT INTO PORT FREEPORT GATE



### DIRECTIONS


FROM DOW OYSTER CREEK, PLANT A & SHINTECH

- ► FROM OYSTER CREEK TAKE SH523 TO SH288
- ► CONTINUE SOUTH ON 523 AROUND AND OVER THE BRIDGE
- ► TURN LEFT INTO PORT FREEPORT GATE



### DIRECTIONS

- ► FROM CP CHEM TURN RIGHT ONTO SH35
- ► CONTINUE ON SH35 AND TURN RIGHT ONTO SH36
- ► CONTINUE TO SH523 AND TURN LEFT
- CONTINUE PASSED THE RR TRACKS AND TURN RIGHT INTO PORT FREEPORT GATE



#### DIRECTIONS

- ► FROM TENARIS TURN RIGHT ONTO SH35
- ► CONTINUE ON SH35 AND TURN RIGHT ON SH36
- ► CONTINUE ON SH36 AND TURN LEFT ON SH523
- CONTINUE PASSED THE RR TRACKS AND TURN RIGHT INTO PORT FREEPORT GATE

#### WHAT TYPE OF PERMIT IS RIGHT FOR YOU?

VIEW ALL AVAILABLE PERMITS TO DETERMINE THE BEST OPTION FOR YOUR BUSINESS

<u>HTTPS://WWW.TXDMV.GOV/MOTOR-CARRIERS/OVERSIZE-</u> <u>OVERWEIGHT-PERMITS/TETXAS-SIZE-WEIGHT-LIMITS</u>